


PARTS LIST

JACK SHAFT PARTS

SPENCER PORTA-RIG MODEL 7000



Part No.	Description	No. Req'd
JS-7M-1	Shaft	1
JS-7M-15	Drive Sprocket	1
JS-7M-6	Hy-Drive Sprocket	1
JS-7M-4	Bearing Retainer Plate	2
JS-7M-5	Bearing Housing	1
JS-7M-16	Bearing Retainer Plate	2
JS-7M-7	Spacer	2
JS-7M-8	Spacer	1
JS-7M-32	Yoke	1
JS-7M-31	Sliding Jaw Clutch	1
JS-7M-9	Spacer	1

Part No.	Description	No. Req'd
JS-7M-29	Stationary Jaw Clutch	1
JS-7M-10	Spacer	1
JS-7M-39	Bearing Retainer Plate	1
JS-7M-11	Spacer	1
JS-7M-17	Hydraulic Pump Drive Sprocket	1
JS-7M-3	Bearing Housing	1
JS-7M-13	Spacer	1
JS-7M-2	Low Drive Sprocket	1
	SKF 22218 Bearings	2
	55195 Seals	6
	Timken 681 Cones	2
	Timken 672 Cups	2

FOR REFERENCE ONLY
 For **SPENCER-HARRIS** Parts
 Call **1-870-234-3264**
 Magnolia, Arkansas