




# PARTS LIST

## CROWN BLOCK ASSEMBLY

### SPENCER PORTA-RIG MODEL 7000




FOR REFERENCE ONLY  
 For **SPENCER-HARRIS** Parts  
 Call **1-870-234-3264**  
 Magnolia, Arkansas

# PARTS LIST

# CROWN BLOCK ASSEMBLY (Continued)

## SPENCER PORTA-RIG MODEL 7000

### SCHEMATIC DIAGRAM



Part No.	Description	No. Req'd
CB-7MA	Complete Crown Block Assembly	
CB-7M-7	Sheave — 28"	5
CB-7M-4	Pin — Short	1
CB-7M-3	Pin — Long	1
CB-7M-5	Nut — Pin	2
CB-7M-6	Washer — Thrust	10
A5226TS	Bearing — Hyatt	5

FOR REFERENCE ONLY  
For **SPENCER-HARRIS** Parts  
Call **1-870-234-3264**  
Magnolia, Arkansas